

1002508/2021/O/o AXEN/BR.D/HQ/SCR

दक्षिण मध्य रेलव
प्रमुख मुख्य इंजीनियर का कार्यालय,
पांचवीं मंजिल, रेल निलयम
सिकंदराबाद- 500 071



SOUTH CENTRAL RAILWAY
Office of the Principal Chief Engineer,
Vth Floor, Rail Nilayam
SECUNDERABAD - 500 071

File.No.W.71/BR/Bridge/Policy/Vol.II

Dt:28.09.2021

CAO/C/SC, CPM/RVNL/SC,BZA,CHENNAI
DRM/SC,HYB,BZA,GTL,GNT & NED

Sub: Construction and maintenance of Cover Over Platforms and FOBs-reg
Ref: This office letter no.W.71/Br/Bridge/Policy, dated 25.04.2016.

Vide this office letter under reference, guidelines were issued that seating arrangement around columns of COP & FOBs are not to be done to facilitate easy accessibility of primary members for inspection and maintenance. It is once again reiterated that these instructions shall be followed by all concerned while executing the works of COP/FOBs.

Receipt of this letter may please be acknowledged.

K Ramakrishna
28/9/2021
(K RAMAKRISHNA)
Chief Bridge Engineer

Copy to: Sr.DEN/Co-ord/SC,BZA/GTL,HYB,GNT & NED for information and necessary action please