



ए०के०दादरया
A.K.Dadrya
का०निदेशक/पूल एवं संरचना
Ex. Director/B&S

भारत सरकार – रेल मंत्रालय
अनुसंधान अभिकल्प और मानक संगठन
लखनऊ-226011
Government of India – Ministry of Railways
Research Designs & Standards Organisations
Lucknow-226011
Phone/Fax: 0522-2450398
Email:edbsrdso@gmail.com

No. CBS/DPG/1

Dated 01-01-2018

Principal Chief Engineer:

1. Central Railway, Mumbai CST-400 001.
2. Eastern Railway, Fairlie Place, Kolkata-700 001.
3. East Central Railway, Hazipur-844 101.
4. East-Coast Railway, Bhubaneshwar-751 016.
5. Northern Railway, Baroda House, New Delhi-110 001.
6. North-Central Railway, Allahabad-211 001.
7. North Eastern Railway, Gorakhpur-273 001.
8. North-Western Railway, Jaipur-302 001.
9. Northeast Frontier Railway, Maligaon, Guwahati-781 061.
10. Southern Railway, Park Town, Chennai-600 003.
11. South Central Railway, Rail Nilayam, Secunderabad-500 371.
12. South East Central Railway, Bilaspur-495 004.
13. South Eastern Railway, Garden Reach, Kolkata-700 043.
14. South-West Railway, Hubli-580 023.
15. Western Railway, Mumbai-400 020.
16. West-Central Railway, Jabalpur-482 001.

Sub:- Provision of Side Pathways on Girder Bridges.

Ref:- Railway Board's letter No. 2017/53/CE-III/BR/Side Pathway dated 27-11-17.

(1) Vide reference above; Railway Board has advised to issue the drawings for Standard spans with provision of side pathway. RDSO has explored the possibility to provide the side pathway and issued the drawings, which is also applicable in existing girders. Details of typical arrangement of pathway for composite and open web girders are given below:-

S.No.	Subject	Drawing No.
1	Side Pathway on Composite girder, parallel to track	CBS- 0046
2	Side Pathway on Open Web Girder, parallel to track	CBS- 0045

(2) While other drawings related to Side Pathway on steel plate girder, Inspection platform and pedestal for Bearing had already been issued. Details with drawing no are given below:-


S.No.	Subject	Drawing No.
1	Side Pathway on steel plate girder parallel to track	CBS-0042-0042/3
2	Inspection platform and pedestal for Bearing	CBS-0016

(3) All above mentioned drawings has been uploaded on RDSO Website; this can be accessed through rail net 10.100.2.4: B&S Directorate – B&S Drawings – Side Path Way.

(A.K.Dadrya)
01/01/2018
Executive Director/B&S
For Director General

Copy for information and necessary action to:-

- I. Chief Administrative Officer (Constn.):
 1. Central Railway, Chhatrapati Shivaji Terminus, Mumbai -400 001.
 2. Eastern Railway, N.K.G. Building, 14 Strand Road (4th Floor), Kolkata-700 001.
 3. East Central Railway, Mahendru Ghat, Patna-800 004.
 4. East-Coast Railway, Bhubaneshwar-755 001.
 5. Northern Railway, Kashmere Gate, Delhi- 110 006.
 6. North-Central Railway, Allahabad-211 001.
 7. North-Eastern Railway, Gorakhpur- 273 001.
 8. N.F. Railway, Maligaon, Guwahati-781 011.
 9. North-Western Railway, Near Jawahar Circle, Maliviya Nagar, Jaipur-302 006.
 10. Southern Railway, 183, EVR Periyar, High Road Egmore, Chennai -600 008.
 11. South Central Railway, Rail Nilayam, Secunderabad-500 371.
 12. South East Central Railway, Bilaspur-495 004.
 13. South-Eastern Railway, Garden Reach, Kolkata-700 043.
 14. South-Western Railway, 18, Basaveshwara (Millers) Road, Bangalore-560 046.
 15. Western Railway, Churchgate, Mumbai-400 020.
 16. West-Central Railway, Jabalpur-482 001.
- II. Director General, Railway Staff College, Vadodara (Gujarat),
- III. Director, IRICEN, Pune-410 001.
- IV. Executive Director, Civil Engg. (B&S), Railway Board, New Delhi-110 001.
- V. Managing Director, RITES LTD., RITES Bhawan, Plot No.1, Sec.29, Gurgaon (Haryana)-122001.
- VI. Managing Director, IRCON, Palika Bhawan, Sector XIII, R.K. Puram, New Delhi.
- VII. CAO/Northern Railway, USBRL Project, Satyam Resort Complex, Trikuta Nagar Extn., Jammu Tawi-180 012.
- VIII. CAO/ERS/Southern Railway, Ernakulam, Kerala-682 506.


(A.K. Dadrya)
Executive Director/B&S
For Director General