



SOUTH CENTRAL RAILWAY

Headquarters Office,
Works Branch,
Rail Nilayam, 5th Floor
Secunderabad-500025

No. W.71/Br.L/Genl.

Dated: 07-06-2021

Sr.DENs/Co-ord/SC, BZA, GTL, HYB, GNT & NED

Sub: Attention to RUB/Bridge Rebuilding locations – Reg.

Ref: 1. This office letter of even no. dated 02-06-2020

2. Standard instructions for monsoon patrolling and watching of vulnerable locations issued vide letter no. W.363/P/Vol.XIV dated 19-05-2021

Many RUB / Bridge rehabilitation works have been completed during the last 6 months (after the end of monsoon 2020) where RCC BOXes were inserted into the track. As the approach portion of these bridges is prone for settlement during the current year monsoon, these bridges shall be kept under watch during the monsoon period. Stationary watchman shall invariably be posted at such locations whenever there is rainfall in the section. Speed Restriction shall be imposed wherever settlement is noticed and prompt action shall be taken to attend to the approaches.

In addition, pumping arrangements shall be made to remove water stagnation during heavy rains at RUB locations where problem has been experienced during earlier monsoons and where Drain works have not been fully completed. Flooring and other protection works should also be completed expeditiously at all waterway bridges.

(K. Rama Krishna)
Chief Bridge Engineer

Copy: CE/RSW, CE/BRH, CE/WS&F for information.